




Stand pipe

* not illustrated

Item	Description	NO
1*	stand pipe up to 250 bar complete	27.01.00
2*	stand pipe up to 250 bar complete	27.04.36
3	stand pipe up to 250 bar complete	27.01.10
4*	head of stand pipe for compressor type SRT - MOD	27.01.20
5	head of stand pipe for stationary compressor	27.01.16
6	separator tube	27.01.22
7	riser	27.01.23
8	tube clamp with fitting	27.01.24
9	stud bolt M 16 x 38	27.01.25
10	hexagon screw M 10 x 1 x 15	27.01.26
11	gasket ring A 10 x14 (copper)	3.11.03
12*	shutter an fastening part complete	27.01.30
13	shutter an fastening part	27.01.31
14	screw plud M 12 x 1,5	27.01.32
15	gasket ring A 12 x 18 (copper)	1.11.05
16	o-ring 82 x 5,5	27.03.15
17	o-ring 55 x 3	27.03.16
18	pipe cock valve "Schmölle" see 21.01.15	
19	drainage tube 8 X 1 / l=1200mm with solder tube 27.01.46	27.01.45
20	solder tube with nozzie	27.01.46
21	o-ring 11 x 2,5	26.14.04
22	union screw R 5/8"	26.14.03
23	air pipe - pressure retaining valve to stand pipe	27.05.10
24	tube flange for tube 16 x 3	27.03.01
25	cutting ring	40.20.09
26	union nut	40.20.10
27	adjustable angle screwing 16-5	40.10.12
28	pressure retaining valve see 17.20.00	
30*	stand pipe up to 300bar	27.04.37
31*	stand pipe up to 300bar	27.04.38
32	stand pipe 300bar	27.02.11
33*	peaces items 4-17	diverse
34*	peaces item 18 to 22	diverse
40	o-ring 19 x 2,5	27.03.00
41	hexagon nut M 16	27.03.03
42	lock washer A 16	27.03.04



Stand pipe

* not illustrated

Item	Description	NO
43	hexagon nut M 30 x 1,5	27.03.11
44	lock washer A 30	27.03.12
45	hold clip	27.03.13
46	hexagon screw M 12 x 30	27.03.14
47	stud bolt M 12 x 30	4.10.10
48	hexagon nut M 12	1.10.05
49	disk	14.70.52
50	lock washer A 12	12.51.03
51	double hollow screw M 8	16.80.55
52	ring piece	13.11.17
53	gasket ring A 8 x 14 (copper)	5.11.03

